

# **APPENDIX D**

## **Photo Log**





**Photo 1** View east from WQ-01 sample site, located within the Reference Wetland. Photo taken on May 28, 2020.



**Photo 2** View west from WQ-01 sample site, located within the Reference Wetland. Photo taken on May 28, 2020.



**Photo 3** View north from WQ-01 sample site, located within the Reference Wetland. Photo taken during spring sampling on May 28, 2020.



**Photo 4** View south from WQ-01 sample site, located within the Reference Wetland. Photo taken during fall sampling on May 28, 2020.



**Photo 5** View east from WQ-01 sample site, located within the Reference Wetland. Photo taken during fall sampling on October 15, 2020.



**Photo 6** View west from WQ-01 sample site, located within the Reference Wetland. Photo taken during fall sampling on October 15, 2020.





**Photo 7** View north from WQ-01 sample site, located within the Reference Wetland. Photo taken on October 15, 2020.



**Photo 8** View south from WQ-01 sample site, located within the Reference Wetland. Photo taken on October 15, 2020.



**Photo 9** View east from WQ-02 sample site, located within Wetland 06. Photo taken during spring sampling on May 28, 2020.



**Photo 10** View west from WQ-02 sample site, located within Wetland 06. Photo taken during spring sampling on May 28, 2020.



**Photo 11** View north from WQ-02 sample site, located within Wetland 06. Photo taken during spring sampling on May 28, 2020.



**Photo 12** View south from WQ-02 sample site, located within Wetland 06. Photo taken during spring sampling on May 28, 2020.





**Photo 13** View east from WQ-02 sample site, located within Wetland 06. Photo taken during fall sampling on October 15, 2020.



**Photo 14** View west from WQ-02 sample site, located within Wetland 06. Photo taken during fall sampling on October 15, 2020.



**Photo 15** View north from WQ-02 sample site, located within Wetland 06. Photo taken during fall sampling on October 15, 2020.



**Photo 16** View of ground conditions from WQ-02 sample site, located within Wetland 06. Photo taken during fall sampling on October 15, 2020.



**Photo 17** View east from WQ-03 sample site, located within Wetland 06. Photo taken during spring sampling on May 28, 2020.



**Photo 18** View west from WQ-03 sample site, located within Wetland 06. Photo taken during spring sampling on May 28, 2020.





**Photo 19** View north from WQ-03 sample site, located within Wetland 06. Photo taken during spring sampling on May 28, 2020.



**Photo 20** View south from WQ-03 sample site, located within Wetland 06. Photo taken during spring sampling on May 28, 2020.



**Photo 21** View east from WQ-03 sample site, located within Wetland 06. Photo taken during fall sampling on October 15, 2020.



**Photo 22** View west from WQ-03 sample site, located within Wetland 06. Photo taken during fall sampling on October 15, 2020.



**Photo 23** View north from WQ-03 sample site, located within Wetland 06. Photo taken during fall sampling on October 15, 2020.



**Photo 24** View northeast from WQ-03 sample site, located within Wetland 06. Photo taken during fall sampling on October 15, 2020.





**Photo 25** View northeast from WQ-06 sample site, located downslope of the SWCRR Project and Wetland 08. Photo taken during spring sampling on May 28, 2020.



**Photo 26** View southeast from WQ-06 sample site, located downslope of the SWCRR Project and Wetland 08. Photo taken during spring sampling on May 28, 2020.



**Photo 27** View east from WQ-06 sample site, located downslope of the SWCRR Project and Wetland 08. Photo taken during spring sampling on May 28, 2020.



**Photo 28** View northwest from WQ-06 sample site, located downslope of the SWCRR Project and Wetland 08. Photo taken during spring sampling on May 28, 2020.



**Photo 29** View northeast from WQ-06 sample site, located downslope of the SWCRR Project and Wetland 08. Photo taken during fall sampling on October 15, 2020.



**Photo 30** View southeast from WQ-06 sample site, located downslope of the SWCRR Project and Wetland 08. Photo taken during fall sampling on October 15, 2020.





**Photo 31** View east from WQ-06 sample site, located downslope of the SWCRR Project and Wetland 08. Photo taken during fall sampling on October 15, 2020.



**Photo 32** View northwest from WQ-06 sample site, located downslope of the SWCRR Project and Wetland 08. Photo taken during fall sampling on October 15, 2020.



**Photo 33** View east from WQ-07 sample site, located downslope of the SWCRR Project and Wetland 08. Photo taken during spring sampling on May 28, 2020.



**Photo 34** View southeast from WQ-07 sample site, located downslope of the SWCRR Project and Wetland 08. Photo taken during spring sampling on May 28, 2020.



**Photo 35** View northeast from WQ-07 sample site, located downslope of the SWCRR Project and Wetland 08. Photo taken during spring sampling on May 28, 2020.



**Photo 36** View west from WQ-07 sample site, located downslope of the SWCRR Project and Wetland 08. Photo taken during spring sampling on May 28, 2020.





**Photo 37** View southeast from the dry WQ-07 sample site, located downslope of the SWCRR Project and Wetland 08. Photo taken during fall sampling on October 15, 2020.



**Photo 38** View south from the dry WQ-07 sample site, located downslope of the SWCRR Project and Wetland 08. Photo taken during fall sampling on October 15, 2020.



**Photo 39** View north from the dry WQ-07 sample site, located downslope of the SWCRR Project and Wetland 08. Photo taken during fall sampling on October 15, 2020.



**Photo 40** View west from the dry WQ-07 sample site, located downslope of the SWCRR Project and Wetland 08. Photo taken during fall sampling on October 15, 2020.



**Photo 41** View southwest from WQ-04b sample site, located downslope of the SWCRR Project and Wetland 08. Photo taken during spring sampling on May 28, 2020.



**Photo 42** View north from WQ-04b sample site, located downslope of the SWCRR Project and Wetland 08. Photo taken during spring sampling on May 28, 2020.





**Photo 43** View west from WQ-04b sample site, located downslope of the SWCRR Project and Wetland 08. Photo taken during spring sampling on May 28, 2020.



**Photo 44** View of ground conditions at the WQ-04b sample site, located downslope of the SWCRR Project and Wetland 08. Photo taken during spring sampling on May 28, 2020.



**Photo 45** View southwest from WQ-04b sample site, located downslope of the SWCRR Project and Wetland 08. Photo taken during fall sampling on October 15, 2020.



**Photo 46** View north from WQ-04b sample site, located downslope of the SWCRR Project and Wetland 08. Photo taken during fall sampling on October 15, 2020.



**Photo 47** View west from WQ-04b sample site, located downslope of the SWCRR Project and Wetland 08. Photo taken during fall sampling on October 15, 2020.



**Photo 48** View east from WQ-04b sample site, located downslope of the SWCRR Project and Wetland 08. Photo taken during fall sampling on October 15, 2020.





**Photo 49** View northwest from WQ-05b sample site, located downslope of the SWCRR Project and Wetland 09. Photo taken during spring sampling on May 28, 2020.



**Photo 50** View north from WQ-05b sample site, located downslope of the SWCRR Project and Wetland 09. Photo taken during spring sampling on May 28, 2020.



**Photo 51** View east from WQ-05b sample site, located downslope of the SWCRR Project and Wetland 09. Photo taken during spring sampling on May 28, 2020.



**Photo 52** View south from WQ-05b sample site, located downslope of the SWCRR Project and Wetland 09. Photo taken during spring sampling on May 28, 2020.



**Photo 53** View northwest from WQ-05b sample site, located downslope of the SWCRR Project and Wetland 09. Photo taken during fall sampling on October 15, 2020.



**Photo 54** View north from WQ-05b sample site, located downslope of the SWCRR Project and Wetland 09. Photo taken during fall sampling on October 15, 2020.





**Photo 55** View east from WQ-05b sample site, located downslope of the SWCRR Project and Wetland 09. Photo taken during fall sampling on October 15, 2020.



**Photo 56** View south from WQ-05b sample site, located downslope of the SWCRR Project and Wetland 09. Photo taken during fall sampling on October 15, 2020.



**Photo 57** View east upstream of the WQ-4a sample site, located upslope of the SWCRR Project within Wetland 08. Photo taken during spring sampling on May 28, 2020.



**Photo 58** View south from WQ-4a sample site, located upslope of the SWCRR Project within Wetland 08. Photo taken during spring sampling on May 28, 2020.



**Photo 59** View west from WQ-4a sample site, located upslope of the SWCRR Project within Wetland 08. Photo taken during spring sampling on May 28, 2020.



**Photo 60** View east from WQ-4a sample site, located upslope of the SWCRR Project within Wetland 08. Photo taken during spring sampling on May 28, 2020.





**Photo 61** View west from WQ-4a sample site, located upslope of the SWCRR Project within Wetland 08. Photo taken during fall sampling on October 15, 2020.



**Photo 62** View northeast from WQ-4a sample site, located upslope of the SWCRR Project within Wetland 08. Photo taken during fall sampling on October 15, 2020.



**Photo 63** View south from WQ-4a sample site, located upslope of the SWCRR Project within Wetland 08. Photo taken during fall sampling on October 15, 2020.



**Photo 64** View southwest from WQ-4a sample site, located upslope of the SWCRR Project within Wetland 08. Photo taken during fall sampling on October 15, 2020.



**Photo 65** View east of the WQ-5a sample site, located upslope of the SWCRR Project within Wetland 09. Photo taken during spring sampling on May 28, 2020.



**Photo 66** View south of the WQ-5a sample site, located upslope of the SWCRR Project within Wetland 09. Photo taken during spring sampling on May 28, 2020.





**Photo 67** View north of the WQ-5a sample site, located upslope of the SWCRR Project within Wetland 09. Photo taken during spring sampling on May 28, 2020.



**Photo 68** View west of the WQ-5a sample site, located upslope of the SWCRR Project within Wetland 09. Photo taken during spring sampling on May 28, 2020.



**Photo 69** View east of the WQ-5a sample site, located upslope of the SWCRR Project within Wetland 09. Photo taken during fall sampling on October 15, 2020.



**Photo 70** View south of the WQ-5a sample site, located upslope of the SWCRR Project within Wetland 09. Photo taken during fall sampling on October 15, 2020.



**Photo 71** View north of the WQ-5a sample site, located upslope of the SWCRR Project within Wetland 09. Photo taken during fall sampling on October 15, 2020.



**Photo 72** View west of the WQ-5a sample site, located upslope of the SWCRR Project within Wetland 09. Photo taken during fall sampling on October 15, 2020.





**Photo 73** View upstream (southwest) of the FL-01 inflow site. Photo taken during spring sampling on May 28, 2020.



**Photo 74** View downstream (northeast) of the FL-01 inflow site. Photo taken during spring sampling on May 28, 2020.



**Photo 75** View of ground conditions at the FL-01 inflow site. Photo taken during spring sampling on May 28, 2020.



**Photo 76** View of ground conditions at the FL-01 inflow site. Photo taken during spring sampling on May 28, 2020.



**Photo 77** View upstream (southwest) of the FL-01 inflow site. Photo taken during fall sampling on October 15, 2020.



**Photo 78** View downstream (northeast) of the FL-01 inflow site. Photo taken during fall sampling on October 15, 2020.





**Photo 79** View of ground conditions at the FL-01 inflow site. Photo taken during fall sampling on October 15, 2020.



**Photo 80** View of ground conditions at the FL-01 inflow site. Photo taken during fall sampling on October 15, 2020.



**Photo 81** View upstream (south) of the FL-02 Inflow site. Photo taken during spring sampling on May 28, 2020.



**Photo 82** View downstream (north) of the FL-02 Inflow site. Photo taken during spring sampling on May 28, 2020.



**Photo 83** View west of the FL-02 Inflow site. Photo taken during spring sampling on May 28, 2020.



**Photo 84** View east of the FL-02 Inflow site. Photo taken during spring sampling on May 28, 2020.





**Photo 85** View upstream (south) of the FL-02 Inflow site. Photo taken during fall sampling on October 15, 2020.



**Photo 86** View downstream (north) of the FL-02 Inflow site. Photo taken during fall sampling on October 15, 2020.



**Photo 87** View downstream (north) of the FL-02 Inflow site. Photo taken during fall sampling on October 15, 2020.



**Photo 88** View downstream (north) of the FL-02 Inflow site. A beaver dam located at the downstream extent of the inflow channel prevents surface connectivity between the Channel and Wetland 06. Photo taken during fall sampling on October 15, 2020.



**Photo 89** View southwest of the FL-03 Inflow site. Photo taken during spring sampling on May 28, 2020.



**Photo 90** View northeast of the FL-03 Inflow site. Photo taken during spring sampling on May 28, 2020.





**Photo 91** View of ground conditions at the dry FL-03 Inflow site. Photo taken during spring sampling on May 28, 2020.



**Photo 92** View of ground conditions at the dry FL-03 Inflow site. Photo taken during spring sampling on May 28, 2020.



**Photo 93** View southwest of the FL-03 Inflow site. Photo taken during fall sampling on October 15, 2020.



**Photo 94** View northeast of the FL-03 Inflow site. Photo taken during fall sampling on October 15, 2020.



**Photo 95** View of ground conditions at the dry FL-03 Inflow site. Photo taken during fall sampling on October 15, 2020.



**Photo 96** View of ground conditions at the dry FL-03 Inflow site. Photo taken during fall sampling on October 15, 2020.





**Photo 97** View southwest of the FL-04 outflow site. Photo taken during spring sampling on May 28, 2020.



**Photo 98** View northeast of the FL-04 outflow site. Photo taken during spring sampling on May 28, 2020.



**Photo 99** View of ground conditions at the dry FL-04 outflow site. Photo taken during spring sampling on May 28, 2020.



**Photo 100** View of ground conditions at the dry FL-04 outflow site. Photo taken during spring sampling on May 28, 2020.



**Photo 101** View southwest of the FL-04 outflow site. Photo taken during fall sampling on October 15, 2020.



**Photo 102** View northeast of the FL-04 outflow site. Photo taken during fall sampling on October 15, 2020.





**Photo 103** View of ground conditions at the dry FL-04 outflow site. Photo taken during fall sampling on October 15, 2020.



**Photo 104** View of ground conditions at the dry FL-04 outflow site. Photo taken during fall sampling on October 15, 2020.